


SRI 400PIV, 10MA

Note 1 - This jumper strap may be removed if ungrounded low impedance outputs are desired.



Tub 12A (Inp

12A

12B

12A

6L6GC (Both T

5U4

## VOLTAGE AND RESISTANCE CHART

ha	Din No	DC Volts	DC Volts	AC Volts	Resistance
be AX7	Pin No.	No Signal	at 30W out	at 30W out	Unit off
put)	1	134	120	1 2	220754
,ραι,	1	1		1.3	330K*
	2	0	0	0.24	1 M
	3	1.2	1.1	0.22	3.3K
	4&5	Fil	6.3 V. ac to Pin 9	-	0 to 70
	6,7,8	-	. <del>-</del>	-	-
	9	Fil	-	-	0 to 70
AU7	1	270	235	9	40*
	2	134	120	13	330K*
	3&8	138	126	0.57	18K
	4&5	Fil	6.3 V. ac to Pin 9	_	0 to 70
	6	270	235	9	43K*
	7	110	100	Ó	26M*
	9	Fil		_	l .
	<b>_</b>			-	0 to 70
вн7	1	355	295	132	12K*
	2	0	0	9	220K
	3&8	16	14	0.32	1.2K
	4&5	Fil	6.3 V. ac to Pin 9		0 to 70
	6	355	295	132	12 <b>K</b> *
	7	0	0	9	220K
	9	Fil	-	7	1
		}	2/5	_	0 to 70
AX7	1	440	365	94	185*
	2	-46	-46	134	1 M
	3	-45	-45	118	270K
	4&5	Fil	6.3 V. ac to Pin 9	-	0 to 70
	6	440	365	94	185*
	7	-46	-46	134	l M
	8	-45	-45	118	270K
	9	Fil	-	-	0 to 70
C/1614	1	0	0	0	
Tubes)	2	Fil	6.3 V. ac to Pin 7		0 to 70
	3	440	365	94	200*
	4	440	365	94	1
	5	-45	-45	i	200*
	6	i l	-45	118	270K
	6 7	- E:1	-	-	-
	8	Fil	-	<b>-</b>	0 to 70
	8	1.1	2.7	94	25
lGВ	1	-	-	_	· -
	2	455	400	7.9 (Ripple)	0*
	3	-	-	, ,==- <b>F</b> F==,	_
		395 AC	385 AC	385	45
	<b>4</b> 5	-		303	
	6	395 AC	385 AC	385	1 -
	7	3/3 AC	- 100 AC	303	45
	8	455	400		0*